

FIG. 3

FIG. 4A




FIG. 4A




FIG. 4B




FIG. 4C

09943432-080701



FIG. 5



FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10

104030-2441600




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15

00943432-080704

FIG. 16





FIG. 16

102030 2242450




CRAIN BUZZ	002114012038	0.12 A
CRAIN BUZZ	002114012038	0.12 A
PRICE ADJUST	000000033301 F	0.12-A
CRAIN BUZZ	002114012038	0.12 A
PRICE ADJUST	000000033301 F	0.12-A
EXCENTIA	008669988178K	1.00 J
ST TIRE FEE	060538850389K	1.75 H
ST TIRE FEE	060538850389K	1.75 H
EXCENTIA	008669988178K	1.00 J
ST TIRE FEE	060538850389K	1.75 H
ID REQUIRED - 21		
BAILEYS	008676721009	1.00 A
Tax		0.21
Total \$		8.58


Scale Display

0.00 lb


0min = 01 lb nmax = 3000

CLASS III 10°C to 40°C







Age Restricted




Overview




No Barcode




Coupons




Payment Options




Scanning Tips



Alcohol & Tobacco



Need Assistance



Return

FIG. 17






FIG. 19





FIG. 20